



STATE OF WISCONSIN
DEPARTMENT OF NATURAL RESOURCES

LAKE SURVEY MAP

CRANBERRY LAKE
VILAS-ONEIDA COUNTY
SEC. 30, 31, 32, 6 T. 39-40 N. R. 10-11 E.



EQUIPMENT RECORDING SONAR MAPPED JUNE 1969
MONTH YEAR
LAKE BOTTOM SYMBOLS

- | TOPOGRAPHIC SYMBOLS | | LAKE BOTTOM SYMBOLS | |
|-----------------------|------------------------|---------------------|-----------------------------|
| (B) Brush | Steep slope | P. Peat | B Boulders |
| (PW) Partially wooded | ~ Indefinite shoreline | Mk. Muck | ⚡ Stumps & Snags |
| (W) Wooded | ~ Marsh | C. Clay | ⚡ Rock danger to navigation |
| (C) Cleared | ~ Spring | M. Marl | T Submergent vegetation |
| (P) Pastured | ~ Intermittent stream | Sd. Sand | ⊥ Emergent vegetation |
| (A) Agricultural | ~ Permanent inlet | Sl. Silt | ⊥ Floating vegetation |
| B.M. Bench Mark | ~ Permanent outlet | Gr. Gravel | ⊥ Brush shelters |
| ■ Dwelling | ~ Dam | B. Rubble | |



◆ Access ◆ Access with Parking ◆ Boat Livery

SPECIES OF FISH	ABUNDANCE		
	Abundant	Common	Present
Muskie			X
N. Pike			X
Walleye	X		
L.M. Bass			X
S.M. Bass			X
S. Bass			X

WATER AREA 955.5 ACRES
 UNDER 3 FT. 19.8 %
 OVER 20 FT. 0.4 %
 MAX. DEPTH 23 FEET.
 TOTAL ALK. 31 P.P.M.
 VOLUME 8949.9 ACRE FT.