



STATE OF WISCONSIN
DEPARTMENT OF NATURAL RESOURCES

LAKE SURVEY MAP

ECHO LAKE ONEIDA COUNTY
SEC. 32,33 T. 39 N. R. 9 E.



B.M. "X", is the highest point on the S.E. corner of cement Highway "D" bridge on inlet at east end of lake. Taken 7/69.
Elev. = 100.00'
Water level = 92.50'



EQUIPMENT RECORDING SONAR MAPPED JULY 1969

TOPOGRAPHIC SYMBOLS		LAKE BOTTOM SYMBOLS	
(B) Brush	Steep slope	P. Peat	B Boulders
(PW) Partially wooded	- - - Indefinite shoreline	Mk. Muck	☼ Stumps & Snags
(W) Wooded	☼ Marsh	C. Clay	☼ Rock danger to navigation
(C) Cleared	☼ Spring	M. Marl	T Submergent vegetation
(P) Pastured	~ Intermittent stream	Sd. Sand	⌞ Emergent vegetation
(A) Agricultural	≡ Permanent inlet	St. Silt	⌞ Floating vegetation
B.M. Bench Mark	≡ Permanent outlet	Gr. Gravel	⌞ Brush shelters
(D) Dwelling	≡ Dam	R. Rubble	



Access Access with Parking Boat Livery
Drawn by: T. Ginder

SPECIES OF FISH	Abundance		
	Abundant	Common	Present
Muskie			X
N. Pike			X
Walleye			X
L.M. Bass			X
S.M. Bass			X
Panfish			X

WATER AREA 106.57 ACRES
UNDER 3 FT. 16 %
OVER 20 FT. 0 %
MAX. DEPTH 18 FEET.
TOTAL ALK. 19 P.P.M.
VOLUME 865.35 ACRE FT.
SHORELINE 2.3 MILES